

Sanapiro Monument Renovation Work Site Report 13/06/2024

***Description of Work :** Renovation of Sanapiro Monument Area.

1-Electrical cable on the floor is not protected properly. 25 meter length. If curbs are under control of ours, needs repair.



2-Solar panel system is not working at all. An electrician should check it and find out the problem.



3-Cameras are not working (4 cameras). An electrician should check.



4-If this wall is under control ours, needs repair. Plastering + painting.



5- Spot light should be checked whether working or not.

