

## Bulbul Monument Renovation Work Site Report 13/06/2024

**\*Description of Work :** Renovation of Bulbul Monument.

1-Marble on the floor is broken, rain water comes into joint. Total 3 m2 need to renew.



2-No electricity there. Lights are not working. (1 spot light was not there)



3-Concrete bollars are not fixed on the floor. 4 pieces are moving. 1 piece is not there.



4-Bulbul monument needs renovation or cleaning.



5- Marble decors need cleaning/polishing. Total 5 piece, 120 cm radius, 50 cm height.



6- "BÜLBÜL" written non aesthetically in latin alphabet. L is small, Ü dots are very big.

